**Photo Index and Description**
**Heritage Trust Fund 2007 Grand Application**
**Seneca Main Street Historic District , A.K.A. Pony Express Museum (The Building)**
February 24, 2007

| File Name | Brief Description |
|---|---|
| 0 Final Cover | Southwest Elevation, Northeast View of The Building. Picture taken: January 23, 2007 by Dean Rial. |
| Final Attachment #1 | Historic View of The Building. Southern Elevation, Northern View. Picture taken in 1901. Photo courtesy of Al Buser. |
| Final Attachment #2 | Historic View of The Building. Southwest Elevation, Northeast View. Picture taken in 1915. |
| Final Attachment #3 | Front Façade. Southern Elevation, Northern View. Photo taken: January 23, 2007, by Dean Rial. |
| Final Attachment #4 | Front Façade, brick and mortar. Southern Elevation, Northern View. Photo taken: January 23, 2007, by Dean Rial. |
| Final Attachment #5 | Masonry joints. Southern Elevation, Northern View. Photo taken: January 23, 2007, by Dean Rial. |
| Final Attachment #6 | Front Façade Brick and window crowns. Southern Elevation, Northern View. Photo taken January 23, 2007, by Dean Rial. |
| Final Attachment #7 | Front Façade; left entry; columns and lintels. Southern Elevation, Northern View. Photo taken January 23, 2007, by Dean Rial. |
| Final Attachment #8 | Front Façade; right entry; columns and lintels and foundation stones. Southern Elevation, Northern View. Photo taken: January 23, 2007, by Dean Rial. |

| | |
|---|---|
| Final Attachment #9 | Front Façade; cast stone window sills. Southern Elevation, Northern View. Photo taken: February 17, 2007, by Dean Rial. |
| Final Attachment #10 | Front Façade; trim. Southern Elevation, Northern View. Photo taken: January 23, 2007, by Dean Rial. |
| Final Attachment #11 | Front Façade: left entry , awning arms and exterior woodwork. Southern Elevation, Northern View. Photo taken: January 23, 2007, by Dean Rial. |
| Final Attachment #12 | Front Façade: right entry, awning arms and exterior woodwork. Southern Elevation, Northern View. Photo taken: January 23, 2007, by Dean Rial. |
| Final Attachment #13 | Front Façade; corner exterior stone lintel sign and trim. Southwestern Elevation, Northeastern View. Photo taken: January 23, 2007 by Dean Rial. |
| Final Attachment #13 | Front Façade: flashing patch at center protrusion. Southern Elevation, Northern View. Photo taken: January 23, 2007 by Dean Rial. |

SS
TT
RR
AA
TT
HH
MM
AA
NN
SS

1901.

SIMON'S
FAIR.
GROCERIES.

JAN 23 2007

RECHOW'S VARIETY
THE POPULAR STORE
WITH POPULAR PRICES

STRATHMANS

JAN 23 2007

JAN 23 2007

JAN 23 2007

CLOSED
NY EXPRESS RERIDE
JAN 23 2007

CLOSED
FOR THE
SEASON
JAN 23 2007

JAN 23 2007

MUSEUM
JAN 23 2007

JAN 23 2007

SS
TT
RR
AA
TT
HH
MM
AA
NN
S'S